

Crossover protection using (4) DZ-1070's and (2) DZ-1008's and (2) DZ-1008's

Point to Point Track

Break in track to isolate block must occur before train can reach Sensors.

Loop Track

DZ-1070
Only needed if this track is bi-directional

